

DENSO HOLDTIGHT

DESCRIPTION

Denso HoldTight is an additive that prevents flash rusting of wet abrasive and water blasted iron and steel surfaces and of dry blasted surfaces in a pressurized wash down. It effectively removes all salts, including chlorides, sulphates, phosphates, nitrates, etc and other contaminants, including oil, grease and blast residues. It is approved by most major coating suppliers for use with most coatings.

PRINCIPAL CHARACTERISTICS

Soluble in water Non-hazardous Biodegradable Phosphate free Non-flammable With no rain, temperature above 3°C, rusting will be prevented for about 48 hours, often longer Raises pH of blasting water to help compensate for acidic sand Colorless Leaves no residue Surface salts, including chlorides, undetectable after use Product chemistry approved by the FDA for food grade service under 21 Code of Federal Regulations 178.3400

BASIC DATA

Density (1g/cm³)

Priming should be done as soon as possible, before flash rust appears and after the surface is dry. Some primers can be applied even when the surface is still damp, provided it is free from visible droplets or running water, but a dry substrate is always preferred. Typical Time before coating is 48 hours, or longer with favourable weather conditions, no rain, temperature above 3°C Shelf Life - 3 years when stored in cool & dry place. Do not store below 3°C to avoid freezing.

INSTRUCTIONS FOR USE

Denso HoldTight is typically used in both blast water and wash down water. It is diluted with water at 2% wt/wt, depending on the application, humidity, and level of surface contamination. It is rarely necessary to dilute it less than 50:1 and frequently possible to dilute it much more. 100:1 is the most common dilution ratio

In high humidity environments with highly contaminated substrates (e.g., steel plate used in ocean service or exposed to dirty air), 50:1 may be necessary for both cycles. With low humidity and a relatively clean surface, 100:1 dilution on the blast cycle and 100:1 on the wash down should be satisfactory. Until a job begins, assume an average of 100:1 for all the water you plan to use.

NOTE: Water that contains a high concentration of salts, carbonates and bicarbonates (i.e., hard water), or other contaminants may interfere with the performance of Denso HoldTight. Hard water may also be a problem for some equipment. Consult the manufacturer. In most localities, water treatment on site is accessible and inexpensive. Industrial or plant water is often a problem, so should be avoided. In a few areas, even potable ("drinking") water may also be a problem. In most cases "bad" water can be corrected easily and inexpensively. Call our technical service staff if you have any concerns or questions about water. If you follow these instructions and Denso HoldTight is not working as you expect, it is probable that you have a water problem. Call our staff immediately.



LEADERS IN CORROSION PREVENTION AND SEALING TECHNOLOGY

TECHNICAL DATA SHEET

OVER 130 YEARS SERVICE TO INDUSTRY



ISO 9001:2008 Certified

Document Reference: TDS323/11.07 Rev: 01

Avoid "pooling" of Denso HoldTight treated water, on flat areas, excess water should be blown away with oil-free compressed air.

Though you will usually have a 48-hour or longer rust free window, it is good practice to prime as soon as possible after the surface is dry and before flash rust appears.

SAFETY PRECAUTIONS

Wear eye protection when handling this or similar products. In case Denso HoldTight gets into eyes, flush with water for 5-10 minutes. See a doctor if irritation persists. Inhalation of vapour of undiluted HoldTight may be harmful to some individuals.

Important

Winn & Coales / Denso SA (Pty) Ltd pursue a policy to develop and continually improve all of our products and therefore the information given in this data sheet is intended as a general guide and does not constitute a warranty of specification. However, our sales personnel are committed to assist the user in establishing the suitability of the product for its intended purpose and additional specific information is available on request.

Denso SA (Pty) Ltd operate a Quality Management System registered to ISO 9001:2008.

Head Office / Factory: 120 Malacca Road, Red Hill, Durban. P.O.Box 201259, Durban North, 4016, South Africa
Tel: +27 (031) 569 4319 Fax: +27 (031) 569 4328 Email: bid@denso.co.za Website: www.denso.co.za
